

Transparencies for Screen Printing

1. Laserprint image onto LASERPRINT transparency.
(DO NOT USE A INKJET TRANSPARENCY IN LASER PRINTER!!!!)
2. Inkjet image onto INKJET transparency. (some work and some don't, so you may have to experiment with your particular printer.)
3. Go to Kinkos/Fed Ex and have them print 2 transparencies for you.
Then stack them ontop of one another and shoot onto screen.
4. Use baby oil or vegetable oil to make image on paper transparent.
 - 1- Lay paper on sheet of newsprint on glass slabs.
 - 2- Pour a puddle of vegetable oil on top and move around with a red rag.
 - 3- Flip over and repeat on back side.
 - 4- Blot paper between two clean sheets of newsprint to get excess oil off.
(you may need to add a little more time to exposure, depending on the thickness of the paper)

Kinkos/Fed Ex can sometimes print larger images for transfers or transparencies.